

Hardwick Vermont Site Visit /Field observations and 2003-2004 Winter History

1. On February 3,2004 Jessie Stanley and I drove to Hardwick Vermont to reinstall the control box that provides remote control of the data collection rate and activates and deactivates flood lights at the Hardwick Vermont field site. Also seasonal ice thickness measurements were made and observations of ice conditions upstream and downstream of the ICS. This ice season has had two ice runs so far this winter, the first occurring on December 12th **Fig 4-5** followed by a second release and documented by the Hardwick Web camera on January 15th 2004 following a severe cold snap **Fig 11**. This second event resulted in the creation of an ice jam upstream of the Cottage Street Bridge **Fig 15**.Just downstream of this location heavy frazil ice accumulations required the town to use mechanical removal techniques to improve river flow. **Fig16** (Memo for record Tuthill 17 December 2003.)
2. Ice thickness measurements were made in the pool upstream **Fig 17-18** of the structure and photo's show the condition of the ice and the remnants of the release on January 15th and the additional accumulation of ice between the 3rd and 4th structural element on the left bank side of the river. **Fig 17and 19**.
3. The instrumentation shelter located at the ICS site is used to monitor water levels at 11 locations along the Lamoille River upstream and downstream of the ICS along with air and water temperatures and a web camera **Fig 12**. The control box installation was completed and tested, lights and time lapse video deck was set up and also tested at the shelter. The tape deck was set for 12hour time laps setting to allowing maximum coverage during daylight hours. Readings of the water level data indicate that we currently have only two of our 11 sensors available due to the extreme cold and low flow conditions leading up to the current site visit. A warming trend may thaw sensors and bring them back on line. A new power supply was added to the instrumentation package this year to remove a suspected source of power fluctuations to the data collection system.

Table of figures:

Fig 1 Map of Hardwick Vermont ICS project watershed

Fig 2 USGS Air Photo of Hardwick Vermont

Fig 3 Map of Hardwick Vermont

Fig 4 Web Photo December 12,2003

Fig 5 Web photo December 12,2003

Fig 6 Lamoille River High Flow event looking towards the left bank on November 30,2003

Fig 7 High Flow event looking upstream November 30,2003

Fig 8 Web Photo January 13,2004

Fig 9 Web Photo January 14,2004

Fig 10January 15,2004 ICS Following Ice Run overnight Hardwick Web Camera

Fig 11 Weather History Morrisville, Vermont January 15,2004

Fig 12 Sensor layout on Lamoille River Hardwick Vermont Fig 12

Fig 13 USGS Air photo of Hardwick Vermont from USGS 30 April 1999 at ICS location

Fig 14 Ice jam location on February 3,2004 from January 15th ice release


Fig 15 Ice jam location on February 3,2004 looking upstream of cottage street bridge

Fig 16 Looking downstream of Cottage Street Bridge at the refrozen channel on February 3,2004 after ice removal

Fig 17 Pool area upstream of ICS on February 3,2004 with a one foot ice cover and evidence of the January 15,2004 ice run along the banks

Fig 18 Ice thickness measurements in the pool upstream of the ICS


Fig 19 ICS with new one-foot thick ice cover formation on February 3,2004



Hardwick Vermont Watershed (Fig 1)



USGS Air Photo Hardwick Vermont ICS (Fig 2)



Hardwick Vermont Contour Map (Fig 3)



Hardwick Vermont ICS Hardwick Vermont ICS November 30,2003 (Fig 4)



Debris accumulation at Hardwick Vermont ICS November 30,2003 (Fig 5)



Looking upstream Ice run on or before 12/12/03 (Fig 6)



Remnants of Ice run on or before 12/12/03 Web cam photo from right bank (Fig 7)




January 13,2004 Lamoille River Looking upstream at ICS partial ice cover
Hardwick Web Camera (Fig 8)



January 14,2004 Complete Freeze Up upstream of ICS Hardwick Web Camera (Fig 9)



ICS Following Ice Run overnight Hardwick Web Camera (Fig10)




History for Morrisville, Vermont on Thursday, January 15, 2004

Copyright © 2004 [The Weather Underground, Inc.](http://www.the-weather-underground.com)

Temperature records from a nearby town of Morrisville indicate the extreme cold snap prior to the ice release at the Hardwick ICS on 15 January 2004. (Fig 11)

HARDWICK TRANSDUCER LOCATIONS 9/10/03



Transducer locations 9/10/2003

#	New Tran	Distance (ft)	Invert elevation	Transducer Type	Year	Old # loc	Feature
1		0		Submerged	2002	1	
2	222	New		Submerged	2003	14	New location (rt bank)
3	250		846.12	Air	2003	6	F.P
ICS	290			ICS	2002	ICS	ICS
4	302			Submerged	2002	12	
5	310			Submerged	2002	13	
6	319			Submerged	2002	11	
7	351			Submerged	2002	10	
8	398			Submerged	2002	9	
9	460			Submerged	2002	2	
10	573			Submerged	2002	7	
11	1304	New		Submerged	2003	4	New sub Railroad
12	2162	Na		Submerged	2002	3	Removed

Note


Old Tran location #5 not used

Thermistors #34 and #36 moved to old location #8 (525ft) measuring bed temperature


Thermistors #32 and #33 at Tran location #1 measuring bed temperature

Transducer at location 12 removed 9/11/03

Sensor layout on Lamoille River Hardwick Vermont (Fig 12)



Air photo of Hardwick Vermont from USGS 30 April 1999 at ICS location (Fig 13)



Ice jam location on February 3, 2004 from January 15th ice release (Fig 14)



Ice jam location on February 3, 2004 looking upstream of cottage street bridge (Fig 15)



Looking downstream of Cottage Street Bridge at the refrozen channel on February 3, 2004 after ice removal (Fig 16)



Pool area upstream of ICS on February 3,2004 with a one foot ice cover and evidence of the January 15,2004 ice run along the banks (Fig 17)

Hole #	Dist from rt. bk. (Ft)	Total depth (Ft)	Ice thick. (Ft)	Frazil
1	13	1.6	0.8	None
2	30	2.4	1.05	None

Ice thickness measurements in the pool upstream of the ICS (Fig 18)



ICS with new one-foot thick ice cover formation on February 3,2004 (Fig 19)